



**MERCEDES CLA SHOOTING BRAKE: 1KSH864**

Vinnnumber:	<b>WDD1179081N228447</b>	Versionname:	<b>2.1 CLA 200 CDI SHOOTING BRAKE</b>
First Registrationdate:	<b>23/06/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>55712</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>SERVICEBEURT A5 OVER 25 DAGEN</b>	Parking lot:	<b>1410</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-artificial leather</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

<b>Total cost ex VAT</b>	<b>373,50</b>
--------------------------	---------------



<b>Bonnet, Stone chip(s), Acceptable</b>	<b>0,00</b>
--	-------------

*No pictures to display*

<b>Wing R L, Chemical polution, Acceptable</b>	<b>0,00</b>
--	-------------

*No pictures to display*

<b>Alloy rim F R, Scratch(es), Acceptable</b>	<b>0,00</b>
---	-------------

<i>No pictures to display</i>		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Chemical polution, Acceptable		0,00
<i>No pictures to display</i>		
Door R L, Chemical polution, Acceptable		0,00
<i>No pictures to display</i>		
Tailgate, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Chemical polution, Acceptable		0,00
<i>No pictures to display</i>		
Tailgate, Chemical polution, Acceptable		0,00
<i>No pictures to display</i>		
Sill outer L, Scratch(es), LI - Repair and paint (complete)		310,50
		
Bumper R, Dent(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Chemical polution, Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Roof pillar R, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Windscreen, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Dent(s), PDR - Paintless dent repair		63,00
		
Wing R R, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		