


AUDI A6: 1HNC722

Vinnumber:	WAUZZZ4G2EN180369	Versionname:	A6 AVANT 136PK
First Registrationdate:	26/08/2014	Fiscalpower:	
Expertise Mileage:	184740	Power Kw:	100
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2505
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	Tow bar removable
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/16/98 H LightMetal			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1454,37
Bumper R, Scratch(es), LI - Repair and paint (complete)			254,16



Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Roof, Dent(s), Acceptable	0,00
No pictures to display	
Door F R, Scratch(es), 67 - Polish	0,00
No pictures to display	
Sill outer L, Deformed / Strained, Forfeit	48,00




Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	264,21
---	--------



Bonnet, Scratch(es), 67 - Polish	0,00
No pictures to display	
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	369,84



Floor covering F L, Hole, E - Replace	264,00
---------------------------------------	--------



Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	