



**FORD GRAND C-MAX: 1JXZ746**

Vinnumber:	<b>WF0HXXGCBHFK38873</b>	Versionname:	<b>1.6 TDCI 85KW S/S TREND STYLE</b>
First Registrationdate:	<b>17/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>134577</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2223</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/55/16/93 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>581,76</b>
Bumper R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Door frame R L, Dent(s), It - Spot repair	<b>115,56</b>



Internal Boot Lining L, Scratch(es), Acceptable

0,00



Trunk lid covering R, Scratch(es), Smart repair

110,64



Door F R, Bad repair, P - Check

0,00



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Luggage space cover, Missing, E - Replace

240,00



Wing F L, Dent(s), It - Spot repair

115,56



Door R L, Bad repair, P - Check

0,00



Seat adjuster F L, Crack, Acceptable

0,00



Door R L, Dent(s), Acceptable

0,00

No pictures to display

Door F L, Bad repair, P - Check

0,00



Bumper F, Stone chip(s), Acceptable

0,00

No pictures to display

Tailgate, Dent(s), Acceptable

0,00

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display