



OPEL Vivaro 2900: 1GVE326

Vinnumber:	WOLF7B1B1EV632334	Versionname:	VIVARO 2900 B/F MWB L2H1 DPF(EU5) 115PK
First Registrationdate:	9/05/2014	Fiscalpower:	
Expertise Mileage:	229645	Power Kw:	84
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV13
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/65/16/107 V Steel				
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	2270,86
-------------------	----------------

Bumper R, Dent(s) and scratch(es), E - Replace	329,40
--	---------------





Door moulding Lower R R, Scratch(es), E - Replace

91,50



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Door trim R R, Scratch(es), E - Replace

91,50



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Trunk door R R, Dent(s) and scratch(es), It - Spot repair

115,56



Trunk door R L, Dent(s) and scratch(es), It - Spot repair

115,56





Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Rocker panel inner F L, Scratch(es), Forfeit 110,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76

