



**FORD S Max: 1JGF473**

Vinnumber:	<b>WF05XXGBWSEA11523</b>	Versionname:	<b>S-MAX Trend Style St/St DPF 115PK</b>
First Registrationdate:	<b>10/12/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>121822</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2625</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/60/16/99 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Firestone: 5 mm</b>	Fr.R.	<b>Firestone: 5 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT		1353,78
Door trim F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper F, Scratch(es), LI - Repair and paint (complete)		254,16



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Dent(s), PDR - Paintless dent repair 63,00



Maintenance book, Missing, E - Replace 0,00

*No pictures to display*

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 468,60



Door trim F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Outer door handle F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Door F R, Dent(s), PDR - Paintless dent repair 63,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

*No pictures to display*

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 410,02

