



MERCEDES CLA SHOOTING BRAKE: 1KTP719

| | | | |
|------------------------------------|--------------------------|--------------|---------------------------------------|
| Vinnumber: | WDD1179081N222942 | Versionname: | 2.1 CLA 200 CDI SHOOTING BRAKE |
| First Registrationdate: | 1/07/2015 | Fiscalpower: | |
| Expertise Mileage: | 12907 | Power Kw: | 100 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | B5 IN 50 DAGEN | Parking lot: | 2212 |
| Maintenance: | OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|---------------------------------------|
| Radio CD | Central consol F |
| GPS storage | Luggage cover |
| GPS storage | SD |
| Windows electric F | |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining semi-artificial leather |
| Type of climate control | Manual climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/55/16/91 V LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|--------------------------------------|-------------|
| Total cost ex VAT | 0,00 |
| Roof, Chemical polution, 67 - Polish | 0,00 |

| | |
|-----------------------------------|------|
| Wing R R, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Roof, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |