



**MERCEDES GLC: 1RBD273**

Vinnumber:	<b>WDC2539051F182905</b>	Versionname:	<b>2.1 GLC 220 D 120KW 4M LAUNCH EDITION</b>
First Registrationdate:	<b>3/11/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>95584</b>	Power Kw:	<b>120</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Light Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3425</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats R heated	
GPS storage		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>235/55/19/101 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

**Assistance equipment**



Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>84,00</b>
-------------------	--------------

Door R L, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

No pictures to display

Alloy rim R R polished, Scratch(es), Acceptable	<b>0,00</b>
-------------------------------------------------	-------------

<i>No pictures to display</i>		
Bumper F, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Dent(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Protection plate M, Deformed / Strained, E - Replace		84,00
		
Rear window, Scratch(es), Acceptable		0,00
		
Door F L, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		