



**BMW 3: 1JJR569**

|                                    |                          |              |                                   |
|------------------------------------|--------------------------|--------------|-----------------------------------|
| Vinnumber:                         | <b>WBA3K91010F913046</b> | Versionname: | <b>3 TOURING 316dA 116PK Aut.</b> |
| First Registrationdate:            | <b>6/01/2015</b>         | Fiscalpower: |                                   |
| Expertise Mileage:                 | <b>153535</b>            | Power Kw:    | <b>85</b>                         |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                       |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                    |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>                  |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                         |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>1109</b>                       |
| Maintenance:                       | <b>PLUS 3300 KM</b>      |              |                                   |
| Battery functioning:               | <b>Yes</b>               |              |                                   |
| Number of doors:                   | <b>5</b>                 |              |                                   |
| Number of seats:                   | <b>5</b>                 |              |                                   |
| Number head rests:                 | <b>5</b>                 |              |                                   |
| Rims summer:                       | <b>Aluminium</b>         |              |                                   |
| Category:                          | <b>Passenger Car</b>     |              |                                   |
| Oil level:                         | <b>OK</b>                |              |                                   |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                   |

**Options**

|                                |                              |                  |                   |
|--------------------------------|------------------------------|------------------|-------------------|
| Radio CD                       |                              | Central consol F |                   |
| GPS storage                    | <b>HD</b>                    | Luggage cover    |                   |
| GPS storage                    |                              | Type of Tow bar  | <b>No Tow bar</b> |
| Windows electric F             |                              |                  |                   |
| Windows electric R             |                              |                  |                   |
| Steering wheel multifunctional |                              |                  |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                  |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                  |                   |
| Type of Lining                 | <b>Lining leather</b>        |                  |                   |
| Type of climate control        | <b>Autom climate control</b> |                  |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                       |       |                       |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>205/60/16/92 W LightMetal</b> |       |                       |       |                       |
| Summer tyres:                    | Fr.L. | <b>Michelin: 4 mm</b> | Fr.R. | <b>Michelin: 4 mm</b> |
|                                  | Re.L. | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |             |
|-------------------|-------------|
| Total cost ex VAT | <b>0,00</b> |
|-------------------|-------------|

|  |             |
|--|-------------|
| Alloy rim F L, Scratch(es), Acceptable | <b>0,00</b> |
|--|-------------|



Bumper R, Scratch(es), Acceptable

0,00



Wing F L, Dent(s) and scratch(es), Acceptable

0,00



Wing F R, Repaired, No repair

0,00



Wing R R, Dent(s), Acceptable

0,00



Seat cover F L, Worn, P - Check

0,00




Bumper F, Repaired, No repair

0,00



Door R L, Dent(s), Acceptable

0,00



Maintenance, Maintenance, P - Check

0,00



Door R R, Dent(s) and scratch(es), Acceptable

0,00

