


BMW 2 ACTIVE TOURER: 1KVC254

Vinnumber:	WBA2C110X0V519254	Versionname:	2.0 218D (100KW) ACTIVE TOURER
First Registrationdate:	10/07/2015	Fiscalpower:	
Expertise Mileage:	95691	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3501
Maintenance:	22000KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/17/91 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		300,64
Backrest cover F L, Worn, Acceptable		0,00



Door R R, Scratch(es), Acceptable

0,00



Trunk lid covering R, Scratch(es), Smart repair

110,64



Glove compartment lid, Scratch(es), Acceptable

0,00



Alloy rim F L, Scratch(es), Acceptable

0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Rocker panel inner R R, Scratch(es), Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Scratch(es), Acceptable

0,00



Bonnet, Stone chip(s), Acceptable

0,00



Door F R, Scratch(es), 67 - Polish 0,00



Door panel F R, Scratch(es), Acceptable 0,00

