


FORD GRAND C-MAX: 1JXZ842

Vinnumber:	WF0HXXGCBHFK38740	Versionname:	1.6 TDCI 85KW S/S TREND STYLE
First Registrationdate:	17/03/2015	Fiscalpower:	
Expertise Mileage:	46409	Power Kw:	85
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	UIT TE VOEREN	Parking lot:	2713
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Type of Tow bar	Tow bar fixed
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS base		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/93 H LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 564,60

Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Maintenance, Maintenance, Execute

0,00



Trunk lid covering R, Scratch(es), Smart repair

134,64



Roof, Dent(s), PDR - Paintless dent repair

102,60



Tailgate, Scratch(es), It - Spot repair

115,56



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80

