



AUDI A4: CK6464

Vinnumber:	WAUZZZ8K9EA023508	Versionname:	A4 AVANT Multitr. 177PK Aut.
First Registrationdate:	21/08/2013	Fiscalpower:	
Expertise Mileage:	106454	Power Kw:	130
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3810
Maintenance:	IN 15200 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/16/95 Y LightMetal			
Summer tyres:	Fr.L. Michelin: 5 mm	Fr.R. Michelin: 5 mm	
	Re.L. Michelin: 6 mm	Re.R. Michelin: 6 mm	

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1902,90

Door panel F L, Scratch(es), Smart repair 110,64



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



