


BMW 1 HATCH: 1RJD910

Vinnumber:	WBA1S710805E57485	Versionname:	2.0 120D (140KW)
First Registrationdate:	3/01/2017	Fiscalpower:	
Expertise Mileage:	157693	Power Kw:	140
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1507
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting LED
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Semperit: 8 mm	Re.R.	Semperit: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	115,56
-------------------	---------------

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rear spoiler, Dent(s) and scratch(es), LI - Repair and paint (complete)	115,56
---	--------



Bumper F, Stone chip(s), Acceptable	0,00
-------------------------------------	------

No pictures to display

Sill outer R, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof pillar R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

No pictures to display