


PEUGEOT 3008: 1JSU879

Vinnumber:	VF30U9HD8FS019078	Versionname:	1.6 HDI 84KW ALLURE
First Registrationdate:	17/02/2015	Fiscalpower:	
Expertise Mileage:	153887	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3511
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Panoramic roof
GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 V LightMetal				
Summer tyres:	Fr.L.	Semperit: 7 mm	Fr.R.	Semperit: 7 mm
	Re.L.	Semperit: 7 mm	Re.R.	Semperit: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2219,96
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door moulding Lower F R, Scratch(es), E - Replace 114,00



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Roof pillar L, Dent(s), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper moulding F, Scratch(es), Acceptable 0,00

No pictures to display

Rear wiper arm, Broken, E - Replace 15,00



Roof, Dent(s), LI - Repair and paint (complete) 481,50



Ignition key, Missing, E - Replace 150,00



Bumper corner R R, Scratch(es), It - Spot repair 115,56



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R polished, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Door moulding Lower R R, Scratch(es), E - Replace 114,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20

