



Toyota Yaris: 1WBZ539			
Vinnumber:	VNKKD3D310A138859	Versionname:	
First Registrationdate:	2/02/2015	Fiscalpower:	
Expertise Mileage:	150144	Power Kw:	55
Bodytype:	Hatchback	Body color:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2821
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Windows electric F		Luggage cover	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	175/65/15/84 T Steel			
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Semperit: 4 mm	Re.R.	Semperit: 4 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			2883,62
Bumper F R, Bad repair, Acceptable			0,00



Door R R, Dent(s), Acceptable			0,00
-------------------------------	--	--	-------------

No pictures to display

Wheel cover R L, Scratch(es), Acceptable			0,00
--	--	--	-------------

No pictures to display

Interior, Dirty, Cleaning

50,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68



Wheel cover F R, Scratch(es), E - Replace

24,00



Ignition key, Missing, E - Replace

150,00

No pictures to display

Seat cover F L, Hole, E - Replace

312,00



Rocker panel inner F L, Scratch(es), Forfeit

115,56



Wheel cover F L, Scratch(es), E - Replace

24,00



Gear shift lever knob, Worn, Acceptable

0,00



Bumper F L, Bad repair, Acceptable

0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

246,56



Trunk lid covering R, Scratch(es), Smart repair

110,64



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)


248,40



Bonnet, Dent(s), Le - Replace and paint

827,76





Wheel cover R R, Missing, E - Replace

24,00



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

241,34

