


LU Volkswagen Golf: 1PXA345

Vinnumber:	WVWZZZAUZFP102342	Versionname:	1.6 TDI 77KW HIGHLINE DSG
First Registrationdate:	5/05/2015	Fiscalpower:	
Expertise Mileage:	102004	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2609
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-Alcantara
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/17/94 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1559,90
Bumper R, Scratch(es), LI - Repair and paint (complete)			211,80



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), 67 - Polish 0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 318,35

