


**VOLKSWAGEN Golf: 1JLF045**

|                                   |                          |              |                                 |
|-----------------------------------|--------------------------|--------------|---------------------------------|
| Vinnumber:                        | <b>WVWZZZAUZEW418860</b> | Versionname: | <b>GOLF BER Trendline 105PK</b> |
| First Registrationdate:           | <b>15/01/2015</b>        | Fiscalpower: |                                 |
| Expertise Mileage:                | <b>127549</b>            | Power Kw:    | <b>77</b>                       |
| Bodytype:                         | <b>Hatchback</b>         | Body color   | <b>Black</b>                    |
| Gearbox:                          | <b>MAN 5 VIT</b>         | Paint type   | <b>Metalic</b>                  |
| Transmission:                     |                          | Rims summer  | <b>Steel</b>                    |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                       |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>1120</b>                     |
| Number of doors                   | <b>5</b>                 |              |                                 |
| Number of seats                   | <b>5</b>                 |              |                                 |
| Number head rests                 | <b>5</b>                 |              |                                 |
| Rims summer                       | <b>Steel</b>             |              |                                 |
| Category                          | <b>Passenger Car</b>     |              |                                 |
| Oil level                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                 |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Front parking sensors        |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional | Type of Tow bar              |
| Radio multimedia               | <b>No Tow bar</b>            |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |
| Adaptive cruise control        |                              |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                             |                       |       |                       |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
|               | <b>195/65/15/91 V Steel</b> |                       |       |                       |
| Summer tyres: | Fr.L.                       | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|               | Re.L.                       | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

**Assistance equipment**

|                                         |            |      |               |
|-----------------------------------------|------------|------|---------------|
| Emergency spare wheel                   | <b>Yes</b> | Jack | <b>Yes</b>    |
| Total cost ex VAT                       |            |      | <b>150,00</b> |
| Bumper F, Scratch(es), Acceptable       |            |      | <b>0,00</b>   |
| <i>No pictures to display</i>           |            |      |               |
| Bonnet, Stone chip(s), Acceptable       |            |      | <b>0,00</b>   |
| <i>No pictures to display</i>           |            |      |               |
| Ignition key, Missing, E - Replace      |            |      | <b>150,00</b> |
| <i>No pictures to display</i>           |            |      |               |
| Wheel covers F, Scratch(es), Acceptable |            |      | <b>0,00</b>   |

|                                          |      |
|------------------------------------------|------|
| Wheel cover F R, Scratch(es), Acceptable | 0,00 |
| No pictures to display                   |      |
| Wing R L, Scratch(es), Acceptable        | 0,00 |
| No pictures to display                   |      |
| Door R L, Scratch(es), 67 - Polish       | 0,00 |
| No pictures to display                   |      |
| Wheel cover R R, Scratch(es), Acceptable | 0,00 |
| No pictures to display                   |      |
| Wing R R, Scratch(es), 67 - Polish       | 0,00 |
| No pictures to display                   |      |