



VOLKSWAGEN GOLF VARIANT: 1PEA063

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber: | WVWZZZAUZGP633689 | Versionname: | 1.6 TDI 81KW TRENDLINE |
| First Registrationdate: | 14/06/2016 | Fiscalpower: | |
| Expertise Mileage: | 178207 | Power Kw: | 81 |
| Bodytype: | Break | Body color: | Dark Blue |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2325 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | Type of Tow bar |
| Radio multimedia | Tow bar fixed |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |
| Adaptive cruise control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------|-------|-----------------------|-------|-----------------------|
| 195/65/15/91 H Steel | | | | |
| Summer tyres: | Fr.L. | Semperit: 4 mm | Fr.R. | Semperit: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | |
|-----------------------|------------|
| Emergency spare wheel | Yes |
|-----------------------|------------|

| | |
|---|--------|
| Total cost ex VAT | 438,00 |
| Trunk lid covering R, Scratch(es), Smart repair | 110,64 |



| | |
|---|--------|
| Bonnet, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R R, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 211,80 |



| | |
|--|--------|
| Wing R L, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) | 115,56 |



| | |
|-----------------------------------|------|
| Bumper F, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |