



**LU Volkswagen Sharan: MK4182**

|                         |                          |              |   |
|-------------------------|--------------------------|--------------|---|
| Vinnnumber:             | <b>WVWZZZ7N2GV215988</b> | Versionname: | <b>2.0 TDI SCR 135KW HIGHLINE BMT DSG</b> |
| First Registrationdate: | <b>23/10/2015</b>        | Fiscalpower: |   |
| Expertise Mileage:      | <b>133503</b>            | Power Kw:    | <b>135</b>                                |
| Bodytype:               | <b>MPV</b>               | Body color:  | <b>Blue</b>                               |
| Gearbox:                | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                            |
| Transmission:           | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                          |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                 |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>2305</b>                               |
| Number of doors:        | <b>5</b>                 |              |   |
| Number of seats:        | <b>7</b>                 |              |   |
| Number head rests:      | <b>7</b>                 |              |   |
| Rims summer:            | <b>Aluminium</b>         |              |   |
| Category:               | <b>Passenger Car</b>     |              |   |
| Oil level:              | <b>OK</b>                |              |   |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD                       |                              | Seats electric F L    |                   |
| GPS storage                    | <b>SD</b>                    | Seats electric F R    |                   |
| GPS storage                    |                              | Sun Roof electric     |                   |
| Windows electric F             |                              | Panoramic roof        |                   |
| Windows electric R             |                              | Central consol F      |                   |
| Cruise Control                 |                              | Front parking sensors |                   |
| Steering wheel multifunctional |                              | Rear parking sensors  |                   |
| Seats F heated                 |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Radio multimedia               |                              |                       |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining leather</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |


**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>225/50/17/98 V LightMetal</b> |       |                          |       |                          |
| Summer tyres:                    | Fr.L. | <b>Continental: 4 mm</b> | Fr.R. | <b>Continental: 4 mm</b> |
|                                  | Re.L. | <b>Other: 7 mm</b>       | Re.R. | <b>Other: 7 mm</b>       |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|   |                |
|---|----------------|
| <b>Total cost ex VAT</b>                      | <b>2624,51</b> |
| <b>Windscreen, Stone chip(s), E - Replace</b> | <b>560,64</b>  |



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 348,09



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Door F R, Scratch(es), LI - Repair and paint (complete) 382,02



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56



Shutter / cover, Missing, E - Replace

10,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Rocker panel inner R R, Dent(s), Acceptable

0,00

*No pictures to display*

Wing R R, Scratch(es), Acceptable

0,00

*No pictures to display*


Door R R, Scratch(es), LI - Repair and paint (complete)

382,02



Tailgate, Repaired, Acceptable

0,00

|   |       |
|---|-------|
| Language, repaired, Acceptable  | 0,00  |
| <i>No pictures to display</i>   |       |
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete)                      | 95,00 |
|  |       |
| Door R L, Scratch(es), Acceptable   | 0,00  |
| <i>No pictures to display</i>   |       |