



**VOLVO V40: 1JXD439**

|                                    |                          |              |                       |
|------------------------------------|--------------------------|--------------|-----------------------|
| Vinnumber:                         | <b>YV1MV8481F2231244</b> | Versionname: | <b>1.6 D2 KINETIC</b> |
| First Registrationdate:            | <b>11/03/2015</b>        | Fiscalpower: |                       |
| Expertise Mileage:                 | <b>71297</b>             | Power Kw:    | <b>84</b>             |
| Bodytype:                          | <b>Hatchback</b>         | Body color:  | <b>Blue</b>           |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>        |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>      |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>             |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>2714</b>           |
| Maintenance:                       | <b>OVER 14468 KM</b>     |              |                       |
| Battery functioning:               | <b>Yes</b>               |              |                       |
| Number of doors:                   | <b>5</b>                 |              |                       |
| Number of seats:                   | <b>5</b>                 |              |                       |
| Number head rests:                 | <b>5</b>                 |              |                       |
| Rims summer:                       | <b>Aluminium</b>         |              |                       |
| Category:                          | <b>Passenger Car</b>     |              |                       |
| Oil level:                         | <b>OK</b>                |              |                       |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                       |

**Options**

|                         |                               |                      |                   |
|-------------------------|-------------------------------|----------------------|-------------------|
| Radio CD                |                               | Central consol F     |                   |
| GPS storage             | <b>HD</b>                     | Luggage cover        |                   |
| GPS storage             |                               | Rear parking sensors |                   |
| Windows electric F      |                               | Type of Tow bar      | <b>No Tow bar</b> |
| Windows electric R      |                               |                      |                   |
| Cruise Control          |                               |                      |                   |
| Type of headlighting    | <b>Headlighting Halogen</b>   |                      |                   |
| Type of GPS             | <b>GPS big screen color</b>   |                      |                   |
| Type of Lining          | <b>Lining fabrics</b>         |                      |                   |
| Type of climate control | <b>Manual climate control</b> |                      |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/55/16/91 H LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Kleber: 4 mm</b>   | Fr.R. | <b>Kleber: 4 mm</b>   |
|               | Re.L.                            | <b>Michelin: 3 mm</b> | Re.R. | <b>Michelin: 3 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>927,30</b> |
|-------------------|---------------|

|   |               |
|---|---------------|
| Bumper F, Scratch(es), LI - Repair and paint (complete) | <b>211,80</b> |
|---|---------------|



Sill outer R, Scratch(es), LI - Repair and paint (complete)

310,50



Rocker panel inner R R, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner R L, Scratch(es), Acceptable

0,00

No pictures to display


Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Rocker panel inner F L, Scratch(es), Acceptable

0,00

No pictures to display


Rocker panel inner F R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Interior, Dirty, Cleaning

25,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

