



VOLVO V70: 1FVX839

Vinnumber:	YV1BW88A1E1296356	Versionname:	V70 D4 Kinetic 163PK
First Registrationdate:	13/11/2013	Fiscalpower:	
Expertise Mileage:	112725	Power Kw:	120
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1526
Maintenance:	BINNEN 14824KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	983,21
-------------------	--------

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------



Wing F L, Scratch(es), LI - Repair and paint (complete)

264,21



Door F L, Scratch(es), Acceptable

0,00



Tires, Out of tolerance, Acceptable

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00




Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Wing R R, Bad repair, LI - Repair and paint (complete)

369,84



Roof pillar R, Dent(s), Acceptable

0,00

