



VOLVO XC90: 1UEU961

Vinnumber:	VV1LFBABDH1184319	Versionname:	2.0 T8 4WD Geartronic Inscription 7PL
First Registrationdate:	18/04/2018	Fiscalpower:	
Expertise Mileage:	66490	Power Kw:	235
Bodytype:	SUV	Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2814
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Seats electric F L	
GPS storage	HD	Seats electric F R	
Windows electric F		Seats F L ventilated	
Windows electric R		Seats F R ventilated	
Cruise Control		Sun Roof electric	
Steering wheel multifunctional		Panoramic roof	
Seats F heated		Central consol F	
Radio multimedia		Luggage cover	
Type of headlighting	Headlighting LED	Front parking sensors	
Type of GPS	GPS big screen color	Rear parking sensors	
Type of Lining	Lining leather	Type of Tow bar	No Tow bar
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

275/45/20/110 V LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Total cost ex VAT	1517,10
Seat cover R, Damaged, Acceptable	0,00



Spoiler R, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper spoiler F, Dent(s) and scratch(es), It - Spot repair

115,56



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Scratch(es), LI - Repair and paint (complete) 382,02



Roof, Chemical polution, Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair 0,00



Door panel R L, Tear, Smart repair 110,64

