



VOLKSWAGEN Transporter: 1DOU203

Vinnumber:	WV2ZZZ7HZCH125313	Versionname:	TRANSP.1000 COMBI SWB 84PK
First Registrationdate:	10/07/2012	Fiscalpower:	
Expertise Mileage:	196552	Power Kw:	62
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4626
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	8		
Number head rests:	8		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining artificial leather		
Type of climate control	No climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/65/16/107 R Steel			
Summer tyres:	Fr.L.	Uniroyal: 8 mm	Fr.R.	Uniroyal: 8 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 8 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	124,50
Bonnet, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Sliding door R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Sidewall FL (LCV), Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Supplementary brake lights, Deformed / Strained, E - Replace	33,00



Rearlight R , Crack, E - Replace

91,50



Rear bulkhead lining, Hole, Acceptable

0,00

No pictures to display