


FORD GRAND C-MAX: 1JXZ754

Vinnumber:	WF0HXXGCBHFK38894	Versionname:	1.6 TDCI 85KW S/S TREND STYLE
First Registrationdate:	17/03/2015	Fiscalpower:	
Expertise Mileage:	65609	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2120
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 H LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		








Total cost ex VAT	327,36
-------------------	--------

Door R R, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display

Alloy rim F R polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Tailgate, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Bad repair, P - Check	0,00
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Repaired, Acceptable	0,00
	
Door R L, Repaired, 67 - Polish	0,00
	
Bumper F L, Scratch(es), It - Spot repair	115,56
	
Door F L, Repaired, 67 - Polish	0,00
	
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Repaired, Acceptable	0,00
	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Maintenance book, Missing, P - Check	0,00
<i>No pictures to display</i>	
Alloy rim R L polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	