



BMW 5 TOURING: 1KXZ856

Vinnumber:	WBA5L11000G323017	Versionname:	2.0 518D (100KW) TOURING
First Registrationdate:	29/07/2015	Fiscalpower:	
Expertise Mileage:	137391	Power Kw:	100
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1311
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	463,65
-------------------	---------------

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	---------------



Bumper F, Chemical polution, 67 - Polish	0,00
--	-------------

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)

348,09



Roof, Chemical polution, 67 - Polish

0,00

No pictures to display