



SMART FORFOUR: XL5353

Vinnumber:	WME4530421Y129081	Versionname:	1.0 52kW Pure
First Registrationdate:	11/10/2017	Fiscalpower:	
Expertise Mileage:	58886	Power Kw:	52
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2415
Number of doors:	5		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Windows electric F		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

165/65/15/81 T LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1517,52
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	169,44





Rearview mirror housing L, Scratch(es), Smart repair

110,64



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Compressor, Missing, E - Replace

0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68



Door R R, Scratch(es), LI - Repair and paint (complete)

254,68



Door F R, Scratch(es), LI - Repair and paint (complete)

254,68




Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Dent(s), LI - Repair and paint (complete)


241,34



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)	232,06
---	--------



Sill outer R, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Roof, Dent(s), Acceptable	0,00
---------------------------	------

No pictures to display