


TOYOTA Auris: 1HJH322

Vinnumber:	SB1Z53JE50E097667	Versionname:	AURIS TOUR.SP.HSD Dynamic CVT 99PK Aut.
First Registrationdate:	1/08/2014	Fiscalpower:	
Expertise Mileage:	176530	Power Kw:	73
Bodytype:	Break	Body color:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4306
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Fulda: 3 mm	Fr.R.	Fulda: 3 mm
	Re.L.	Firestone: 4 mm	Re.R.	Firestone: 4 mm


Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1453,67
Rear window, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Trunk lid covering R, Scratch(es), Smart repair 110,64



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), 67 - Polish 0,00

No pictures to display

Bumper moulding F M, Dent(s), E - Replace 14,40



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80





Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L polished, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80

