



**VOLKSWAGEN Crafter 35 MWB: 1AON026**

Vinnumber:	<b>WV1ZZZ2FZB7004638</b>	Versionname:	<b>CRAFTER 35 LB2C MWB 109PK</b>
First Registrationdate:	<b>21/02/2011</b>	Fiscalpower:	
Expertise Mileage:	<b>131171</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance	<b>NOT OK</b>		
Maintenance	<b>UITVOEREN</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>4</b>		
Number of seats	<b>7</b>		
Number head rests	<b>7</b>		
Rims summer	<b>Steel</b>		
Category	<b>Light Commercial Vehicle</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD	Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of Lining	<b>Lining artificial leather</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>235/65/16/107 R Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT 1375,39

Door R L, Rust, LI - Repair and paint (partial) 150,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair 58,80



Mirror side blinker R, Broken, E - Replace

28,50



Door R R, Rust, LI - Repair and paint (complete)

238,76



Seat cover F R, Hole, Smart repair

64,32



Mirror side blinker L, Broken, E - Replace

28,50



Sill outer R, Rust, LI - Repair and paint (complete)

232,88



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

165,13



Rearlight R , Broken, E - Replace

91,50



Door F R, Dent(s), Acceptable

0,00

No pictures to display

Inner seat cover L, Missing, E - Replace

17,00



Seat cover F L, Damaged, E - Replace

300,00



Steering wheel, Worn, Acceptable	0,00
----------------------------------	------

*No pictures to display*

Maintenance, Maintenance, Execute	0,00
-----------------------------------	------



Dashboard, Hole, Acceptable	0,00
-----------------------------	------

*No pictures to display*