


**BMW 3 GRAN TURISMO: 1LBD573**

|                                    |                          |              |                                      |
|------------------------------------|--------------------------|--------------|--------------------------------------|
| Vinnumber:                         | <b>WBA8Y51090G430203</b> | Versionname: | <b>2.0 318D (100KW) GRAN TURISMO</b> |
| First Registrationdate:            | <b>7/08/2015</b>         | Fiscalpower: |                                      |
| Expertise Mileage:                 | <b>121913</b>            | Power Kw:    | <b>100</b>                           |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                          |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                       |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>                     |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                            |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3509</b>                          |
| Number of doors:                   | <b>5</b>                 |              |                                      |
| Number of seats:                   | <b>5</b>                 |              |                                      |
| Number head rests:                 | <b>5</b>                 |              |                                      |
| Rims summer:                       | <b>Aluminium</b>         |              |                                      |
| Category:                          | <b>Passenger Car</b>     |              |                                      |
| Oil level:                         | <b>OK</b>                |              |                                      |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                      |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Radio CD                       | Central consol F                 |
| Windows electric F             | Luggage cover                    |
| Windows electric R             | Front parking sensors            |
| Cruise Control                 | Rear parking sensors             |
| Steering wheel multifunctional | Type of Tow bar                  |
| Radio multimedia               | <b>Tow bar fixed</b>             |
| Type of headlighting           | <b>Headlighting Xenon</b>        |
| Type of GPS                    | <b>GPS big screen color</b>      |
| Type of Lining                 | <b>Lining artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>     |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>225/55/17/97 W LightMetal</b> |                          |       |                          |
| Summer tyres: | Fr.L.                            | <b>Continental: 4 mm</b> | Fr.R. | <b>Continental: 4 mm</b> |
|               | Re.L.                            | <b>Continental: 4 mm</b> | Re.R. | <b>Continental: 4 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|   |               |
|---|---------------|
| <b>Total cost ex VAT</b>  | <b>315,18</b> |
| <b>Bumper R, Scratch(es), Acceptable</b>                            | <b>0,00</b>   |
| <i>No pictures to display</i>                                       |               |
| <b>Bumper F, Scratch(es), Acceptable</b>                            | <b>0,00</b>   |
| <i>No pictures to display</i>                                       |               |
| <b>Alloy rim R R, Scratch(es), LI - Repair and paint (complete)</b> | <b>95,00</b>  |



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 220,18



Alloy rim F R, Scratch(es), Acceptable 0,00

*No pictures to display*