



AUDI Q5: 1HGV241

Vinnumber:	WAUZZZ8R4EA127157	Versionname:	Q5 150PK
First Registrationdate:	17/07/2014	Fiscalpower:	
Expertise Mileage:	151594	Power Kw:	110
Bodytype:	SUV	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3507
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	CD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/17/104 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 3 mm

Assistance equipment

Emergency spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1483,48
-------------------	----------------

Alloy rim F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete)	382,02
---	---------------



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Bumper F M, Scratch(es), Acceptable

0,00

No pictures to display

Bumper cover R M, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Scratch(es), Acceptable

0,00

No pictures to display


Ceiling, Dirty, Acceptable

0,00

No pictures to display

Rear spoiler, Scratch(es), LI - Repair and paint (complete)

115,56



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

362,02





Door F L, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R L, Dent(s), LI - Repair and paint (complete) 115,56

