



MERCEDES E COUP?: 1LGK124

Vinnumber:	WDD2073011F331504	Versionname:	2.1 E 220 BLUETEC 120KW
First Registrationdate:	22/09/2015	Fiscalpower:	
Expertise Mileage:	68910	Power Kw:	120
Bodytype:	Coupé	Body color:	Light Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3222
Number of doors:	2		
Number of seats:	4		
Number head rests:	2		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/40/18/95 Y LightMetal				
Summer tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1338,60
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00



Tyre F R, Tear, E - Replace

153,60



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L polished, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Tyre F L, Tear, E - Replace

153,60



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Door F R, Dent(s), PDR - Paintless dent repair 122,40

