



FORD TRANSIT COURIER: 1SYJ443

Vinnumber:	WF0WXXTACWHA31867	Versionname:	1.5 TDCi 56kW Trend
First Registrationdate:	18/08/2017	Fiscalpower:	
Expertise Mileage:	160607	Power Kw:	56
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2824
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Rear parking sensors	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/60/15/88 H Steel			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	No
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1704,66
Dashboard, Hole, Smart repair	110,64



Engine protective plate, Broken, E - Replace 64,00



Sill outer R, Dent(s) and scratch(es), Le - Replace and paint 235,50



Wheel cover R L, Missing, E - Replace 22,50



Protection plate M, Deformed / Strained, E - Replace 74,00



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wheel cover R R, Missing, E - Replace 22,50



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Spare wheel, Missing, E - Replace 153,60



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Smart repair 110,64



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Wheel cover F R, Missing, E - Replace 22,50



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Missing, E - Replace 22,50



Trunk door R L, Scratch(es), Acceptable

0,00

No pictures to display