



OPEL VIVARO: 1KJN683

Vinnumber:	W0L3F7012FV633657	Versionname:	1.6CDTI 85KW EDITION SWB 2.9T
First Registrationdate:	12/05/2015	Fiscalpower:	
Expertise Mileage:	121230	Power Kw:	85
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3210
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	Tow bar fixed
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/65/16/107 T Steel			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Total cost ex VAT	962,80
Bumper F, Scratch(es), Smart repair	110,64



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	--------



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Rearview mirror housing R, Scratch(es), Smart repair 110,64



Wing R R, Scratch(es), 67 - Polish 0,00

No pictures to display

Rearview mirror glass R, Broken, E - Replace 13,50



Floor covering F L, Hole, E - Replace 237,00



Rearview mirror glass L, Broken, E - Replace 13,50

