



**SKODA Octavia: 1DFB060**

Vinnumber:	<b>TMBHT21Z2C2179802</b>	Versionname:	<b>OCTAVIA COMBI GTec Ambition DPF 105PK</b>
First Registrationdate:	<b>26/04/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>85757</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4111</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Sun Roof electric	
Windows electric F		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Type of headlighting	<b>Headlighting Halogen</b>	Type of Tow bar	<b>No Tow bar</b>
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>195/65/15/91 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Vredestein: 7 mm</b>	Fr.R.	<b>Vredestein: 7 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

**Total cost ex VAT**

343,40

**Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)**

0,00





Roof, Dent(s), PDR - Paintless dent repair

122,40




Interior, Dirty, Cleaning

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Window F L door, Not functioning (well), I - Repair

0,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Wing F R, Dent(s), PDR - Paintless dent repair

63,00



Door F L, Dent(s), Acceptable

0,00

No pictures to display

Wing F L, Dent(s), PDR - Paintless dent repair

63,00



Door R R, Scratch(es), LI - Repair and paint (complete)

0,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Roof pillar R, Dent(s), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Dent(s), Le - Replace and paint

0,00





Door frame F R, Dent(s), Acceptable

0,00

*No pictures to display*