



VOLKSWAGEN TIGUAN: EE0303

Vinnnumber:	WVGZZZ5NZFW593205	Versionname:	2.0 CRTDI 81KW SPORT&STYLE BMOTION
First Registrationdate:	1/01/2020	Fiscalpower:	
Expertise Mileage:	146853	Power Kw:	81
Bodytype:	SUV	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2805
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/17/96 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1648,35
-------------------	----------------

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Roof pillar R, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Dent(s) and scratch(es), LI - Repair and paint (complete)

481,50





Tailgate, Rust, Acceptable

0,00

