



RENAULT Megane: 1HJK317

Vinnumber:	VF1KZ140651395744	Versionname:	MEGANE BRE Energy GT-Line 110PK
First Registrationdate:	1/08/2014	Fiscalpower:	
Expertise Mileage:	139720	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2628
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	NOT OK
		Wiperblades	OK

Degree of wear

205/50/17/89 V LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Kleber: 4 mm	Re.R.	Kleber: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	401,80
-------------------	---------------

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	-------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00



Door R R, Scratch(es), Acceptable 0,00



MOT Certificate, Extra mileage, P - Check 0,00



Wing R R, Dent(s) and scratch(es), Acceptable 0,00



Door R L, Dent(s), Acceptable 0,00



Roof pillar R, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F L, Scratch(es), Acceptable 0,00



Wing R L, Repaired, No repair 0,00



Maintenance, Maintenance, P - Check 0,00



Wing F R, Dent(s) and scratch(es), Acceptable 0,00



Bonnet, Scratch(es), 67 - Polish 0,00

