



## TOYOTA YARIS: 1KGR630

Vinnumber:	VNKKD3D390A155263	Versionname:	1.5 VVT-I HYBRID COMFORT AUTO
First Registrationdate:	29/04/2015	Fiscalpower:	
Expertise Mileage:	22131	Power Kw:	55
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1110
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

## Options

Windows electric F		Luggage cover	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

## Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

## Degree of wear

	<b>175/65/15/84 T Steel</b>			
Summer tyres:	Fr.L.	Hankook: 6 mm	Fr.R.	Hankook: 6 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm


## Assistance equipment

Emergency spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	0,00
Wheel cover F L, Scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Wing F R, Scratch(es), Acceptable	0,00
No pictures to display	
Boot carpet, Missing, E - Replace	0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 0,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Deformed / Strained, E - Replace 0,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Dent(s), LI - Repair and paint (complete) 0,00



Door F L, Scratch(es), LI - Repair and paint (complete) 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

0,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00

