



AUDI A3: 1HKA238

Vinnumber:	WAUZZZ8VXF1040121	Versionname:	A3 SED Ambition 110PK
First Registrationdate:	6/08/2014	Fiscalpower:	
Expertise Mileage:	84582	Power Kw:	81
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	+ 6500 KM	Parking lot	1431
Maintenance	OK		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	225/45/17/91 Y LightMetal			
	Fr.L.	Pirelli: 8 mm	Fr.R.	Pirelli: 8 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	-----	------	-----

Total cost ex VAT	544,80
-------------------	--------

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display	
------------------------	--

Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display	
------------------------	--

Door F L, Dent(s), Acceptable	0,00
No pictures to display	
Windscreen, Stone chip(s), E - Replace	0,00
 	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing F L, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	259,80
  	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
  	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
  	
Bumper F, Scratch(es), Acceptable	0,00
No pictures to display	
Wing F R, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
    	