



BMW X4: 1KLU765

Vinnumber:	WBAXX110100L95480	Versionname:	XDRIVE20D
First Registrationdate:	29/05/2015	Fiscalpower:	
Expertise Mileage:	106055	Power Kw:	140
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	DEPUIS 13000 KM - 07.2019		
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Sun Roof electric
GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/55/17/103 V LightMetal				
Winter tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	0,00
Tires, Out of tolerance, P - Check	0,00



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display


Maintenance, Maintenance, Execute	0,00
-----------------------------------	------



Mirror side blinker L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Windscreen, Stone chip(s), Windscreen repair	0,00
--	------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display