


**BMW 3 BERLINE: 1KPF181**

|                                   |                                  |              |                                |
|-----------------------------------|----------------------------------|--------------|--------------------------------|
| Vinnumber:                        | <b>WBA3W31080K315190</b>         | Versionname: | <b>2.0 316D (85KW) BERLINE</b> |
| First Registrationdate:           | <b>9/06/2015</b>                 | Fiscalpower: |                                |
| Expertise Mileage:                | <b>36046</b>                     | Power Kw:    | <b>85</b>                      |
| Bodytype:                         |                                  | Body color:  | <b>Brown</b>                   |
| Gearbox:                          | <b>Automatic</b>                 | Paint type:  | <b>Metalic</b>                 |
| Transmission:                     | <b>Back</b>                      | Rims summer: | <b>Aluminium</b>               |
| Fueltype:                         | <b>Diesel</b>                    | Oil level:   | <b>OK</b>                      |
| Maintenance                       | <b>SERVICE IN 12000KM 4 2020</b> | Parking lot: | <b>1109</b>                    |
| Maintenance                       | <b>OK</b>                        |              |                                |
| Battery functioning               | <b>Yes</b>                       |              |                                |
| Number of doors                   | <b>4</b>                         |              |                                |
| Number of seats                   | <b>5</b>                         |              |                                |
| Number head rests                 | <b>5</b>                         |              |                                |
| Rims summer                       | <b>Aluminium</b>                 |              |                                |
| Category                          | <b>Passenger Car</b>             |              |                                |
| Oil level                         | <b>OK</b>                        |              |                                |
| Registration Certificate Car (BE) | <b>Yes</b>                       |              |                                |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Radio CD                       | Central consol F                 |
| GPS storage                    | <b>HD</b>                        |
| GPS storage                    |                                  |
| Windows electric F             |                                  |
| Windows electric R             |                                  |
| Steering wheel multifunctional |                                  |
| Radio multimedia               |                                  |
| Type of headlighting           | <b>Headlighting Halogen</b>      |
| Type of GPS                    | <b>GPS big screen color</b>      |
| Type of Lining                 | <b>Lining artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>     |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>205/60/16/92 W LightMetal</b> |       |                          |       |                          |
| Summer tyres:                    | Fr.L. | <b>Bridgestone: 6 mm</b> | Fr.R. | <b>Bridgestone: 6 mm</b> |
|                                  | Re.L. | <b>Bridgestone: 6 mm</b> | Re.R. | <b>Bridgestone: 6 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 851,30 |
|-------------------|--------|












|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|                                   |      |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|  |       |
|--|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|

|   |   |   |        |
|---|---|---|--------|
|   |   |   |        |
| Door R R, Scratch(es), Acceptable   |   |   | 0,00   |
| <i>No pictures to display</i>   |   |   |        |
| Roof, Chemical pollution, LI - Repair and paint (complete)                        |   |   | 481,50 |
|  |  |   |        |
| Rearview mirror housing L, Scratch(es), Acceptable                                |   |   | 0,00   |
| <i>No pictures to display</i>   |   |   |        |
| Wing F L, Dent(s), PDR - Paintless dent repair                                    |   |   | 63,00  |
|  |  |  |        |
| Bumper F, Scratch(es), LI - Repair and paint (complete)                           |   |   | 211,80 |
|  |  |  |        |
| Alloy rim R L, Scratch(es), Acceptable  |   |   | 0,00   |
| <i>No pictures to display</i>   |   |   |        |