



BMW 3 GRAN TURISMO: 1LBS823

Vinnumber:	WBA8Y51050GJ86890	Versionname:	2.0 318D (100KW) GRAN TURISMO
First Registrationdate:	12/08/2015	Fiscalpower:	
Expertise Mileage:	71501	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3212
Maintenance:	JUNI 2020		
Maintenance:	11000		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			566,60
Wing F L, Dent(s) and scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door R R, Dent(s), Acceptable			0,00

<i>No pictures to display</i>		
Alloy rim R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Seat F L compl, Worn, Acceptable		0,00
<i>No pictures to display</i>		
Wing R R, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)		259,80
		
Alloy rim F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Maintenance book, Missing, Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R L, Dent(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door panel R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bodywork, Not original part, Acceptable		0,00
<i>No pictures to display</i>		
Door F R, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)		211,80

