



PEUGEOT Partner: 476BXL			
Vinnumber:	VF3GJ9HWCAN511743	Versionname:	PARTNER ORIGIN Pack CD AIRCO 75PK
First Registrationdate:	4/08/2010	Fiscalpower:	
Expertise Mileage:	96692	Power Kw:	55
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4405
Number of doors:	6		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Luggage cover	
Windows electric F		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	175/70/14/84 T Steel			
Summer tyres:	Fr.L.	Michelin: 1 mm	Fr.R.	Michelin: 1 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


















Total cost ex VAT	1604,68
Seat cover F L, Hole, E - Replace	360,00



Bumper R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wing R R. Dent(s) and scratch(es). I L - Repair and paint (complete)	308,20
---	---------------

			
Wheel cover R L, Scratch(es), Acceptable			0,00
No pictures to display			
Sliding door R, Repaired, Acceptable			0,00
No pictures to display			
Wing R L, Scratch(es), Acceptable			0,00
No pictures to display			
Dashboard, Scratch(es), Smart repair			110,64
			
Bonnet, Dent(s), Acceptable			0,00
No pictures to display			
Wheel cover F L, Scratch(es), E - Replace			30,00
			
Bumper F, Broken, E - Replace			499,20
			
Bumper R, Dent(s), Smart repair			110,64
			
Wheel cover F R, Scratch(es), E - Replace			30,00
			
Trunk door R R, Dent(s), PDR - Paintless dent repair			63,00
			
Steering wheel, Worn, Acceptable			0,00
No pictures to display			
Trunk door R L, Scratch(es), Acceptable			0,00
No pictures to display			
Wheel cover R R, Scratch(es), E - Replace			30,00



Door R R, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Sliding door R, Dent(s), Acceptable	0,00
-------------------------------------	------

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display