



RENAULT Megane: 1HHL032

Vinnumber:	VF1KZ0R0251167826	Versionname:	MEGANE GT TomTom Edition 95PK
First Registrationdate:	24/07/2014	Fiscalpower:	
Expertise Mileage:	165442	Power Kw:	70
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1727
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H Steel				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	997,31
--------------------------	---------------

Door moulding Lower F L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Outer door handle F L, Scratch(es), LI - Repair and paint (complete)	115,56
---	---------------



Floor covering F L, Hole, Smart repair 64,32



Wheel cover F R, Scratch(es), E - Replace 30,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Door moulding Lower F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Smart repair 110,64




Door R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper corner R L, Scratch(es), It - Spot repair 115,56



Bumper F, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Dent(s), PDR - Paintless dent repair	63,00



Bumper corner R R, Scratch(es), It - Spot repair	115,56
--	--------



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Hole, Smart repair	64,32



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



