


BMW 3: 1JLG458

Vinnumber:	WBA3K910X0F913045	Versionname:	3 TOURING 316dA 116PK Aut.
First Registrationdate:	16/01/2015	Fiscalpower:	
Expertise Mileage:	166366	Power Kw:	85
Bodytype:		Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4627
Maintenance:	IN 27000 KM		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Total cost ex VAT	407,64
Alloy rim R L, Scratch(es), Acceptable	0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel R L, Hole, Smart repair	110,64



Door F L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Outer backrest protection R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Floor covering R, Damaged, E - Replace	252,00



Engine protective plate, Deformed / Strained, E - Replace	45,00
---	-------



Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Outer backrest protection L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Worn, Acceptable	0,00

