



MERCEDES CLA SHOOTING BRAKE: 1KRJ372

Vinnumber:	WDD1179081N183142	Versionname:	2.1 CLA 200 CDI URBAN SHOOTING BRAKE
First Registrationdate:	16/06/2015	Fiscalpower:	
Expertise Mileage:	164311	Power Kw:	100
Bodytype:		Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3226
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/40/18/92 W LightMetal			
Winter tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1184,95
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Roof pillar L, Dent(s), PDR - Paintless dent repair

63,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35

