



MINI 5D: 1SVK434

Vinnumber:	WMWXT710502C16170	Versionname:	2.0 COOPER SD (120 KW)
First Registrationdate:	16/06/2016	Fiscalpower:	
Expertise Mileage:	7781	Power Kw:	120
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1422
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Sun Roof electric
Cruise Control	Panoramic roof
Steering wheel multifunctional	Central consol F
Seats F heated	Luggage cover
Radio multimedia	Rear parking sensors
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Head-up Display	
Sport seats	
	Type of Tow bar
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/45/17/88 V LightMetal			
Winter tyres:	Fr.L.	Hankook: 8 mm	Fr.R.	Hankook: 8 mm
	Re.L.	Hankook: 8 mm	Re.R.	Hankook: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 380,00

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Scratch(es), 67 - Polish 0,00

No pictures to display

Interior, Dirty, Cleaning 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00

