



**MERCEDES CLA SHOOTING BRAKE: 1KTP397**

|                                    |                            |              |   |
|------------------------------------|----------------------------|--------------|---|
| Vinnnumber:                        | <b>WDD1179081N219892</b>   | Versionname: | <b>2.1 CLA 200 CDI URBAN SHOOTING BRAKE</b> |
| First Registrationdate:            | <b>1/07/2015</b>           | Fiscalpower: |   |
| Expertise Mileage:                 | <b>119473</b>              | Power Kw:    | <b>100</b>                                  |
| Bodytype:                          |                            | Body color:  | <b>Grey</b>                                 |
| Gearbox:                           | <b>MAN 6 VIT</b>           | Paint type:  | <b>Metalic</b>                              |
| Transmission:                      | <b>Front</b>               | Rims summer: | <b>Aluminium</b>                            |
| Fueltype:                          | <b>Diesel</b>              | Oil level:   | <b>OK</b>                                   |
| Maintenance:                       | <b>SERVICE A IN 6300KM</b> | Parking lot: | <b>1212</b>                                 |
| Maintenance:                       | <b>OK</b>                  |              |   |
| Battery functioning:               | <b>Yes</b>                 |              |   |
| Number of doors:                   | <b>5</b>                   |              |   |
| Number of seats:                   | <b>5</b>                   |              |   |
| Number head rests:                 | <b>1</b>                   |              |   |
| Rims summer:                       | <b>Aluminium</b>           |              |   |
| Category:                          | <b>Passenger Car</b>       |              |   |
| Oil level:                         | <b>OK</b>                  |              |   |
| Registration Certificate Car (BE): | <b>Yes</b>                 |              |   |

**Options**

|                                |                                       |
|--------------------------------|---------------------------------------|
| Radio CD                       | Central consol F                      |
| GPS storage                    | Luggage cover                         |
| GPS storage                    | <b>SD</b> Front parking sensors       |
| Windows electric F             | Rear parking sensors                  |
| Windows electric R             |                                       |
| Cruise Control                 |                                       |
| Steering wheel multifunctional |                                       |
| Radio multimedia               |                                       |
| Type of headlighting           | <b>Headlighting Xenon</b>             |
| Type of GPS                    | <b>GPS big screen color</b>           |
| Type of Lining                 | <b>Lining semi-artificial leather</b> |
| Type of climate control        | <b>Manual climate control</b>         |
| Sport seats                    |                                       |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |                                |                                |  |
|----------------------------------|--------------------------------|--------------------------------|--|
| <b>225/45/17/91 W LightMetal</b> |                                |                                |  |
| Summer tyres:                    | Fr.L. <b>Bridgestone: 6 mm</b> | Fr.R. <b>Bridgestone: 5 mm</b> |  |
|                                  | Re.L. <b>Continental: 6 mm</b> | Re.R. <b>Continental: 5 mm</b> |  |

**Assistance equipment**

|  |            |            |               |
|--|------------|------------|---------------|
| Repair kit   | <b>Yes</b> | Compressor | <b>Yes</b>    |
| Total cost ex VAT  |            |            | <b>401,80</b> |
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) |            |            | <b>95,00</b>  |



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

