


RENAULT KANGOO EXPRESS: 1JTV519

Vinnumber:	VF1FW18M552415318	Versionname:	1.5DCI 90 5-SEATS MAXI GRAND CONFORT
First Registrationdate:	24/02/2015	Fiscalpower:	
Expertise Mileage:	160591	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4204
Number of doors:	6		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Rear parking sensors	
GPS storage		Type of Tow bar	No Tow bar
GPS storage	SD		
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/95 T Steel			
Summer tyres:	Fr.L.	Other: 5 mm	Fr.R.	Other: 5 mm
	Re.L.	Other: 6 mm	Re.R.	Other: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1428,17
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Crack, E - Replace	395,40



Trunk door panel R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 362,02



Door R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), Smart repair 110,64



Wing R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 22,50



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 22,50



Trunk door panel L, Broken, E - Replace

64,00



Door F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace

22,50



Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Bodywork, Not original part, Acceptable

0,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00

Review minor housing (s), scratches), acceptable

0,00

No pictures to display

Bumper F, Scratch(es), Smart repair

110,64



Wheel cover F L, Scratch(es), E - Replace

22,50



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Ceiling, Damaged, Smart repair

64,32

