



**RENAULT ESPACE: COTTON**

Vinnumber:	<b>VF1RFC00052339598</b>	Versionname:	<b>1.6 DCI 160 EDC ENERGY INTENS</b>
First Registrationdate:	<b>22/07/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>58593</b>	Power Kw:	<b>118</b>
Bodytype:		Body color:	<b>Gold</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>HD</b>	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting LED</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining semi-artificial leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>235/60/18/103 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>179,88</b>
-------------------	---------------

Bonnet, Stone chip(s), Acceptable	<b>0,00</b>
-----------------------------------	-------------

No pictures to display

Door R R, Repaired, Acceptable	<b>0,00</b>
--------------------------------	-------------

No pictures to display

Wing R L, Dent(s), Acceptable	<b>0,00</b>
-------------------------------	-------------

No pictures to display

Seat cover F L, Crack, Smart repair

04,32



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Maintenance book, Missing, E - Replace

0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display