


RENAULT Megane: 1HFZ510

Vinnumber:	VF1BZ0R0250650377	Versionname:	MEGANE BER Life 95PK
First Registrationdate:	10/07/2014	Fiscalpower:	
Expertise Mileage:	87241	Power Kw:	70
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2514
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment


Spare wheel	No	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3763,12
Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	220,18



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)

290,08



Roof pillar L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace

30,00



Wheel cover R L, Scratch(es), E - Replace

30,00



Rocker panel inner F R, Dent(s), LI - Repair and paint (complete)

115,56



Mirror side blinker R, Broken, E - Replace

30,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Floor covering F R, Tear, E - Replace

252,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wheel cover F R, Scratch(es), E - Replace

30,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Rocker panel inner R L, Dent(s), Acceptable 0,00

No pictures to display

Dashboard, Hole, Acceptable 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Backrest cover F L, Hole, E - Replace 360,00



Steering wheel, Worn, Acceptable 0,00

No pictures to display

Spare wheel, Missing, E - Replace 196,80



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Dent(s) and scratch(es), LI - Repair and paint (complete) 481,50



Reversible boot mat, Not original part, Acceptable 0,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 30,00



