



BMW 118 D: HZ5850

Vinnumber:	WBA1S51090V834505	Versionname:	2.0 118D (110KW)
First Registrationdate:	25/10/2016	Fiscalpower:	
Expertise Mileage:	55305	Power Kw:	110
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1312
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/50/17/89 W LightMetal			
	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	139,56
-------------------	---------------

Alloy rim F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display	
------------------------	--

Maintenance, Maintenance, Execute	0,00
-----------------------------------	-------------



Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R L, Dent(s), Acceptable	0,00
No pictures to display	
Certificate Of Conformity, Missing, P - Check	0,00
No pictures to display	
Bonnet, Stone chip(s), Acceptable	0,00
No pictures to display	
Bumper F, Dent(s) and scratch(es), It - Spot repair	139,56
	
Door R R, Dent(s), Acceptable	0,00
No pictures to display	